

9020954

Grisevægt - Grisvåg - Grisevekt - Schweinewaage - Livestock scale

Fejlkode - Felkode - Feilkoder - Fehlermeldungen - Error codes

Error No.	Description
00	No error
11	General scale error (e.g. no connection to load cell)
12	Scale overload (maximum weighing range exceeded)
13	Scale in motion (not settled after 6 seconds)
15	Error taring (e.g. wrong tare format) or Error zero setting (e.g. not in zero range)
20	Scale in underload
31	Transmission error (e.g. data string too long or timeout)
32	Invalid command
33	Invalid parameter
39	Keyboard cannot be unlocked (locked via digital input)

